

ILOCA Services, Inc.

semitrailers.net

THE ILOCA ADVANTAGE

DRY VAN SALES, LEASING SERVICE & PARTS

- ✓ Safety-focused trailer specifications
- ✓ Lower lifetime maintenance costs
- ✓ Parts & service when you need them
- ✓ Trusted partner for 35+ years
- ✓ Free Annual FHWA Inspections*

*At ILoca's service locations

ILoca - Your Full Service Semitrailer Dealership

VXP Plate Wall Van

- Logistic posts on 48" centers = Less Weight
- High Base Rail = Stronger
- Forklift protection
- 101 1/4" interior width
- 99" door opening

VXP - 48" centers



NATIONAL TRAILER CORPORATION
VANGUARD

MaxCube - 16" centers



MaxCube Sheet & Post Van

- Logistic posts on 16" centers = 30% stronger than competitors
- More securement options
- 101" Post-to-post interior width
- 99" door opening

Safety



- Vanguard ICC Bumper Bolt On - Easier Repairs Exceeds Safety Requirements



- Safety Lug Locks & Temp Bolts Added Wheel-end Protection
- ConMet PreSet Plus® Wheel Ends 7 Year Warranty

CONTACT ILOCA NOW!

📍 Aurora, IL

📍 Caledonia, WI

📍 Davenport, IA

📞 844-673-2251

✉️ trailersales@semitrailers.net



SCAN to visit
semitrailers.net

UNITIZED FORKLIFT PACKAGE



27" Reinforced Rear Entry Zone

Forklifts hit the floor hard when loading a van. Most have a thin sheet of diamond plate screwed to the wood in this high traffic area, providing no protection and often trapping moisture underneath. This weakens the floor and leads to rot and collapse.

Vanguard's unitized forklift package provides strength, eliminates the moisture problem, and increases the floor warranty to ten-years, vs the standard five.

Additional cross-members near the threshold impact point and the landing gear wing plates increase strength and durability.

- Unitized, all-steel forklift package vs thin piece of diamond plate nailed to floor
- 27" Reinforced rear entry zone
- Tighter cross-member spacing at landing gear and threshold impact point
- Eliminates moisture which causes floor rot
- Ten-year floor warranty
- Strengthens the entire rear frame

SMART FEATURES

- ✓ Roof Bows on 16" centers from nose to over landing gear, help distribute load to roof, walls, & floor
- ✓ Galvanized components mean less maintenance & higher resale value
- ✓ Internal bulkhead helps prevent forklift punctures
- ✓ Bolt on body components - for easier, faster repairs
- ✓ 99" door opening vs. standard 98"
- ✓ Tire inflations systems - increased tire life & fuel efficiency

ILOca - Your Partner for the Long Haul®

© 2026 ILoca Services, Inc.